

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5 25063 CENTER RIDGE ROAD . WESTLAKE, OH 44145-4114

August 8, 2016

MEMORANDUM

SUBJECT: CWA-NPDES Sampling Inspection at the Sunrise Coal Carlisle Mine in Carlisle,

Indiana

FROM: Jonathan Moody, Environmental Engineer

THRU: Mark Conti, Technical Team Leader MEC

Cleveland Office (ME-W)

TO: Water Enforcement and Compliance Assurance, Section 1

ATTN: Barbara R. VanTil, Section Chief

Enclosed is the report, for your review, summarizing a sampling inspection performed by Jonathan Moody at the Sunrise Coal Carlisle Mine in Carlisle, Indiana. If you have any questions regarding this report, feel free to contact Jonathan Moody at (440) 250-1708.

Attachment

ec: Brooke Furio, ME-W (w/o attachments)

Clean Water Act Inspection Sampling Report

Sunrise Coal LLC, Carlisle Mine 1466 East State Road 58 Carlisle, Indiana 47838

EPA Region 5 Inspection Team:

John Jurevis, EPA Region 5 Water Division Jonathan Moody, EPA Region 5 Office of Enforcement and Compliance Assurance

Dates of Inspection: June 7, 2016 to June 9, 2016

Report Prepared by: Jonathan Moody, Environmental Engineer

U.S. Environmental Protection Agency
Region 5
Office of Enforcement & Compliance Assurance, Cleveland Office
25063 Center Ridge Road, Westlake, OH 44145

TABLE OF CONTENTS

1. SUMMARY OF FIELD ACTIVITIES AND OBSERVATIONS

- 1.1 Objectives of Sampling Effort
- 1.2 Facility Description
- 1.3 Sampling Event Description
- 1.4 Sampling Shipping Information

2. SAMPLING RESULTS

<u>Tables</u>

Table 1 – EPA Sample Collection Information

Table 2 – Field Monitoring Locations and Measurements

Table 3 – Sample Results

Figures

Figure 1 – Sampling Locations

Figure 2 – Sampling Locations Close Up

Figure 3 – Field Conductivity Measurements

Appendix A – Photolog

Appendix B – Chain of Custody Records

Appendix C – Region 5 Chicago Regional Laboratory Analysis Reports for the EPA June 8, 2016 Sampling at the Sunrise Carlisle Mine.

Appendix D – Quality Assurance Project Plan (QAPP)

Appendix E – NPDES Permit No. IN0062791

1. SUMMARY OF FIELD ACTIVITIES AND OBSERVATIONS

1.1 Objective of Sampling Effort

At the request of EPA, Region 5 Water Division, Jonathan Moody from EPA Region 5 Office of Enforcement and Compliance Assurance collected samples in order to check compliance with the Clean Water Act (CWA) and the National Pollutant Discharge Elimination System (NPDES) Permits. Samples were collected with the assistance of John Jurevis from the EPA Region 5 Water Enforcement and Compliance Assurance Branch.

1.2 Facility Description

The Sunrise Coal, LLC. Carlisle Mine consists of an underground coal mining operation and a coal processing plant. Wastewater is generated from the underground mine works, fine coal disposal basin and runoff from coal storage, refuse disposal and other industrial areas. The facility discharges wastewater under two NPDES Permits. An individual permit No. IN0062791 and a permit by rule No. ING040199.

During this inspection, the team sampled two active discharge locations and three instream locations. A summary is provided below:

Outfall 003 – Discharge from a sediment basin located north west of the active coal slurry disposal basin. At the time of the inspection this basin was discharging through a riprap lined overflow. This is monitored under permit ING040199.

Outfall 202 – Discharge from Pond D. At the time of the inspection Pond D was discharging to a riprap lined conveyance. The flow in the conveyance could be flowed for approximately 50 feet from the pond. At this point the flow entered a subsurface conveyance with an unknown outlet. This discharge is monitored under permit ING040199.

Marsh Creek at South County Road 13 SE – Sample collected from the downstream side of roadway crossing. This location is upstream of contribution of Outfall 003 to Marsh Creek.

Marsh Creek at East State Road 58 – Sample collected from the upstream side of roadway crossing. This location is downstream of the contribution of Outfall 003 to Marsh Creek and upstream of the contribution from Outfall 202.

Marsh Creek at South County Road 50 E – Sample collected from the upstream side of roadway crossing. This location is downstream of the contribution of Outfall 003, 202 and the other known discharge locations associated with the preparation plant.

1.3 Sampling Description

On June 8, 2016 EPA personnel collected samples in order to assess compliance with the CWA and the NPDES permits. In addition to the wastewater samples, EPA personnel also used a YSI 556 MPS, serial number 14J1001578, to monitor pH, Conductivity and Dissolved Oxygen at various locations on June 8 and June 9, 2016. The meter was fitted with a YSI 5565 probe for pH measurements, a YSI 5560 probe for Conductivity and a gold foil membrane for the Dissolved Oxygen measurements.

Below is summary of the samples collected by EPA:

TABLE 1							
Sunrise	Sunrise Coal Company – Carlisle Mine – EPA Sample Collection Information						
Sample	Sample	Collection	Sample Description	Sampling Method			
No.	Туре	Date – Time					
S01	water	6/8/16 -	Samples were collected	Grab samples were			
		15:23	from Outfall 003. Samples	collected using a			
			were collected for TSS,	collection jar and			
			TDS, Sulfate, Chloride,	transferred to sample			
			Total Metals and Mercury.	bottles. All samples			

ENFORC	ENIENT CON	FIDENTIAL/	FOIA EXEMPI	I
			Measurements for pH and conductivity were performed in the field.	were placed in a cooler containing ice and preserved as required. The samples were delivered to the Chicago
D.02		5/0/4.5		Region Lab on 6/9/2016.
D02	water	6/8/16 – 15:30	Samples were collected from Outfall 003. Samples were collected for TSS, TDS, Sulfate, Chloride, Total Metals and Mercury. Measurements for pH and conductivity were performed in the field.	Grab samples were collected using a collection jar and transferred to sample bottles. All samples were placed in a cooler containing ice and preserved as required. The samples were delivered to the Chicago Region Lab on 6/9/2016.
S03	water	6/8/16 - 16:15	Samples were collected from Outfall 202. Samples were collected for TSS, TDS, Sulfate, Chloride, Total Metals and Mercury. Measurements for pH and conductivity were performed in the field.	Grab samples were collected using a collection jar and transferred to sample bottles. All samples were placed in a cooler containing ice and preserved as required. The samples were delivered to the Chicago Region Lab on 6/9/2016.
S04	water	6/8/16 – 17:07	Samples were collected from Marsh Creek. Samples were collected for TSS, TDS, Sulfate, Chloride, Total Metals and Mercury. Measurements for pH and conductivity were performed in the field.	Grab samples were collected directly to sample bottles. All samples were placed in a cooler containing ice and preserved as required. The samples were delivered to the Chicago Region Lab on 6/9/2016.
S05	water	6/8/16 – 17:33	Samples were collected from Marsh Creek. Samples were collected for TSS, TDS, Sulfate, Chloride, Total Metals and Mercury. Measurements for pH and conductivity	Grab samples were collected directly to sample bottles. All samples were placed in a cooler containing ice and preserved as required. The samples were

			were performed in the	delivered to the Chicago
			field.	Region Lab on 6/9/2016.
S06	water	6/8/16 —	Samples were collected	Grab samples were
		17:58	from Marsh Creek.	collected directly to
		17.30	Samples were collected for	sample bottles. All
			TSS, TDS, Sulfate,	samples were placed in a
			Chloride, Total Metals and	cooler containing ice and
			Mercury. Measurements	preserved as required.
			for pH and conductivity	The samples were
			were performed in the	delivered to the Chicago
			field.	Region Lab on 6/9/2016.
R07	water	6/8/16 —	Field Blanks for TSS,	Distilled deionized water
		19:17	TDS, Sulfate, Chloride,	from the Chicago
		19.17	Total Metals and Mercury.	Regional Lab was
				transported in 1 gallon
				water cubes. Blank
				samples for TSS, TDS,
				Sulfate, Chloride, Total
				Metals and Mercury were
				poured from the water
				cubes directly to the
				sample bottles. The
				samples were preserved
				as required and placed in
				a cooler with ice.
				The samples were
				delivered to the Chicago
				Region Lab on 6/9/2016.

The facility personnel elected to take their own samples at Outfall 003 and 202 at the same locations and approximately the same times as the EPA samples. The facility used their own bottles and preservatives and declined taking samples at the instream locations.

1.4 Sample Shipping Information

All samples were tagged, placed in a cooler and packed with ice. Custody was maintained during the inspection by locking the samples in an EPA vehicle. Jonathan Moody retained the vehicle keys. After being sealed in a bag in the coolers, the samples were taken by John Jurevis to the Chicago Regional Lab on June 9, 2016. Copies of the chain –of-custody forms are included in Appendix B.

2. SAMPLING RESULTS

TABLE 2	lisle Mine - Field Monitoring Loca	tions and M	easureme	nts		
Monitoring Point	Description	Date	Time	pH (S.U.)	Conductivity (uS/cm)	DO (mg/l)
1	At 004 Outlet, In Pond	6/8/2016	1245	8.82	238	10.42
2	At Channel/Diversion on impoundment	6/8/2016	1455	8.31	470	10.50
3	Pond 003 at Inlet	6/8/2016	1500	8.66	3800	10.15
4	At 003 Outlet in Pond	6/8/2016	1520	8.37	3722	8.14
S01	003 Discharge	6/8/2016	1523	8.17	3747	-
D01	003 Discharge Duplicate	6/8/2016	1530	8.19	3740	-
5	Inlet to Pond D	6/8/2016	1605	7.75	2190	13.79
S03	Outfall at Pond D, 202 or 002 in Pond	6/8/2016	1615	8.94	798	-
S04	Marsh Creek at downstream side of S. County Road 13 SE	6/8/2016	1707	8.34	338	-
S05	Marsh Creek at Upstream Side of E. State Road 58	6/8/2016	1733	7.83	649	-
S06	Marsh Creek at Upstream Side of S. County Road 50 E	6/8/2016	1758	8.14	618	-
6	Coal Storage Collection Sump, west of Pond C.	6/9/2016	845	2.52	5468	6.56
7	West End of Pond C	6/9/2016	850	5.60	5532	6.85
8	Runoff from Refuse Pile	6/9/2016	917	2.06	16266	0.72
9	Ditch by Coal Storage Pile approx. 30 feet upstream of treatment	6/9/2016	926	6.65	6090	7.10
11	Downstream of in-ditch treatment	6/9/2016	930	11.95	7864	6.75
10	Downstream end of culverts from the sediment basin on the south west corner of the covered disposal site.	6/9/2016	933	7.44	2341	7.80
12	Downstream end of culvert with Mine water	6/9/2016	948	7.70	8382	7.66
13	Downstream culvert with pumped flow from underground conveyor at coal storage	6/9/2016	953	4.58	5161	3.40
14	At Pipe from Mine Water	6/9/2016	1008	7.53	8280	4.72
15	Confluence of Prep Plant Yard and culverts with flow from covered refuse	6/9/2016	1026	6.99	2044	5.07
	1					

TABLE 3 Sample Results								
Parameter	Outfall 003 S01	Outfall 003 Duplicate D02	Outfall at Pond D S03	Marsh Creek at S. CR 13 SE S04	Marsh Creek at E. State Rd 58 S05	Marsh Creek at S. CR 50 E S06	Field Blank R07	
Date	6/8/2016	6/8/2016	6/8/2016	6/8/2016	6/8/2016	6/8/2016	6/8/2016	
Time	1523	1530	1615	1707	1733	1758	1917	
Field Measurements								
pH (S.U.)	8.17	8.19	8.94	8.34	7.83	8.14		
Conductivity (uS/cm)	3747	3740	798	338	649	618		
Water Quality								
Total Suspended Solids (mg/l)	15	7	18	U	15	23	U	
Total Dissolved Solids (mg/l)	2650	2660	466	262	514	418	U	
Sulfate (mg/l as SO4) (mg/l)	1330	1350	84.3	26.0 L	143	70.6	0.07 J	
Chloride (mg/l)	417	414	118	33.7 L	71.3	40.2	0.07 J	
Hardness (mg CaCO3/l)	628	623	210	152	229	297	U	
Total Metals								
T. Aluminum (mg/l)	0.367	0.218	0.745	0.828	1.270	0.752	U	
T. Calcium (mg/l)	181	180	41.8	36.8	55.6	70.8	U	
T. Iron (mg/l)	0.367	0.201	0.880	0.55	1.30	0.884	U	
T. Magnesium (mg/l)	42.6	42.2	25.7	14.7	22.0	29.1	U	
T. Arsenic	1.08	1.08	3.03	U	U	1.03	U	
T. Cadmium	6.21	4.59	U	U	1.19	0.50	U	
T. Chromium	U	U	0.89	0.77	1.28	0.89	U	
T. Lead	U	U	0.6	U	0.95	0.81	U	
T. Manganese	1240	1200	162	18.1	299	90.7	U	
T. Nickel	100	95.8	2.53	1.39	12.2	3.86	U	
T. Selenium	11.2	11.2	U	U	U	U	U	
T. Silver	U	U	U	U	U	U	U	
T. Copper	5.21	3.76	1.98	1.4	2.01	1.45	1.73	
T. Zinc	122	100	10.7	U	25.4	10.5	U	

Notes:

All values in ug/l unless noted otherwise

U – Not Detected

J- The identification of the analyte is acceptable; the reported value is an estimate

L- The identification of the analyte is acceptable; the reported values may be biased low. The actual value is expected to be greater than the reported value.





